DEFENSE INFORMATION SYSTEMS AGENCY



P. O. BOX 4502 ARLINGTON, VIRGINIA 22204-4502

REFER TO: Joint Interoperability Test Command (JTE)

9 June 2008

MEMORANDUM FOR DISTRIBUTION

SUBJECT: Extension of the Special Interoperability Test Certification of Cisco CallManager (CCM) Version 4.2(3) Service Release (SR) 3, with Internetwork Operating System (IOS) Software Release 12.4(9) T1

References: (a) DoD Directive 4630.5, "Interoperability and Supportability of Information Technology (IT) and National Security Systems (NSS)," 5 May 2004

(b) CJCSI 6212.01D, "Interoperability and Supportability of Information Technology and National Security Systems," 8 March 2006

- 1. References (a) and (b) establish the Defense Information Systems Agency (DISA), Joint Interoperability Test Command (JITC), as the responsible organization for interoperability test certification. Additional references are provided in the enclosure.
- 2. The CCM Version 4.2(3) SR3 with IOS Software Release 12.4(9) T1 is hereinafter referred to as the system under test (SUT). The SUT meets all of the critical interoperability requirements and is certified for joint use within the Defense Switched Network (DSN) for the following switch types: Private Branch Exchange (PBX) 1 and PBX 2. The SUT meets the VoIP critical interoperability requirements with any certified Assured Services Voice Application Local Area Network (ASVALAN) on the DSN Approved Products List (APL). The identified test discrepancies shown in the SUT Interoperability Summary that remained open after software patches were applied and regression testing was completed have an overall minor operational impact. No other configurations, features, or functions, except those cited within this report, are certified by the JITC, or authorized by the Program Management Office for use within the DSN. This certification expires upon changes that could affect interoperability, but no later than three years from the date of the original memorandum (4 March 2008).
- 3. This is a certification based on a desktop review of the SUT. The original certification was granted based on interoperability testing conducted by JITC, review of vendor's Letters of Compliance (LoC), and review of patches applied to the SUT. Interoperability testing of the CCM Version 4.2(3) with IOS Software Release 12.4(9) T1 was conducted at JITC's Global Information Grid Network Test Facility at Fort Huachuca, Arizona, from 30 October 2006 through 6 January 2007 and documented in reference (c). Review of vendor's LoC was completed on 6 February 2007. Regression testing of CCM Version 4.2(3) SR3 with IOS Software Release 12.4(9) T1 was conducted from 31 October through 3 November 2007. Regression testing of the 7906G, 7942G, 7945G, 7962G, 7965G, and 7975G internet protocol telephones was conducted from 27 through 31 December 2007. A desktop review was requested

to include the Cisco Unified IP Phone Expansion Module 7914. The desktop review was completed on 22 May 2008. JITC analysis determined the Cisco Unified IP Phone Expansion Module 7914 is certified for joint use within the DSN.

- 4. The SUT certified hardware and software components are listed in table 1. The interoperability test summary of the SUT is indicated in table 2. The PBX 1 Capability Requirements (CRs) and Feature Requirements (FRs) are listed in table 3. This interoperability test status is based on the PBX 1's ability to meet:
 - a. DSN services for Network and Applications specified in reference (d).
- b. PBX 1 interface and signaling requirements for trunks/lines specified in reference (e) verified through JITC testing and/or vendor submission of LoC.
- c. PBX 1 CRs/FRs specified in reference (e) verified through JITC testing and/or vendor submission of LoC.
- d. The overall system interoperability performance derived from test procedures listed in reference (f).
- e. Internet Protocol version 6 requirements specified in reference (e), paragraph 1.7, table 1-4, verified through vendor submission of LoC.

Table 1. SUT Hardware and Software Components

CCM Version 4.2(3) SR3, with IOS Software Release 12.4(9) T1					
Component (See note 1.)	Release	Sub-component	Function		
CallManagers MCS7835H, MCS7835I1, MCS7835H2, MCS7825H2, MCS7825H3, MCS7835H1, MCS7825H, MCS 7835I, MCS7845H, MCS7845I, MCS7825-H1, MCS7825I1, MCS7845H1, MCS7845II	CCM 4.2(3) SR3	Not Applicable	Processing/Signaling		
		NM HD 2V	TDM Interface NM HD Voice, 2-slot IP communications voice/fax		
		NM HD 2VE	TDM Interface NM HD Voice, 2-slot IP communications enhanced voice/fax		
		VIC 4FXS/DID	Voice Interface Card, 4-port, RJ-11, Foreign Exchange Station, Direct Inward Dial		
Cisco 3745/3725 Multiservice Access Router (Gateway) (See note 2.)	IOS 12.4(9) T1	VIC2 2FXS	Voice Interface Card, 2-port, RJ-11, Foreign Exchange Station		
Router (Gateway) (See Hote 2.)		VWIC 1MFT T1	Voice/WAN Interface Card 1-port RJ-48, Multiflex Trunk T1		
		VWIC 2MFT T1	Voice/WAN Interface Card 2-port RJ-48, Multiflex Trunk T1		
		VWIC 2MFT T1 DI	Voice/WAN Interface Card 2-port RJ-48, Multiflex Trunk T1, Drop and Insert		
		NM HDV2	TDM Interface NM, HD Voice, 2-slot IP communications enhanced voice/fax		
		VWIC2 2MFT T1/E1	Second Generation Voice/WAN Interface Card 2-port RJ-48, Multiflex Trunk T1/E1 (See note 3.)		
		NM HDV2 2T1/E1	2-port T1/E1 IP Communications HD voice/fax NM, 2 T1/E1 controllers E1 (See note 3.)		
	IOS 12.4(9) T1	NM HDV2 1T1/E1	1-port T1/E1 IP Communications HD voice/fax NM, 2 T1/E1 controllers (See note 3.)		
Cisco 3845/3825 Integrated Services Router (Gateway)		VIC 4FXS/DID	Voice Interface Card, 4-port, RJ-11, Foreign Exchange Station, DID		
		VIC2 2FXS	Voice Interface Card, 2-port, RJ-11, Foreign Exchange Station		
		EM HDA 8FXS	8-port analog Foreign Exchange Station expansion module for voice and fax (See note 4.)		
		EVM HD 8FXS/DID	HD analog and digital extension module for voice and fax		
		VWIC2 1MFT T1/E1	Second Generation Voice/WAN Interface Card 1-port RJ-48, Multiflex Trunk T1/ E1 (See note 3.)		

Table 1. SUT Hardware and Software Components (continued)

CCM Version 4.2(3) SR3 with IOS Software Release 12.4(9) T1 (continued)					
Component (See note 1.)	Release	Sub-component	Function		
		NM HDV2	TDM Interface NM, HD Voice, 2-slot IP		
		TVIVI TID V Z	communications enhanced voice/fax		
		VIC 4FXS/DID	Voice Interface Card, 4-port, RJ-11, Foreign		
			Exchange Station, DID		
		VWIC2 2MFT T1/E1	Second Generation Voice/WAN Interface Card		
			2-port RJ-48, Multiflex Trunk T1/E1 (See note 3.) HD analog and digital extension module for		
		EVM HD 8FXS/DID	voice and fax		
Cisco 2851 Integrated Services Router			8-port analog Foreign Exchange Station		
(Gateway)	IOS 12.4(9) T1	EM HDA 8FXS	expansion module for voice and fax (See note 4.)		
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		NRA HENVA ATTATES	2-port T1/E1 IP Communications HD voice/fax		
		NM HDV2 2T1/E1	NM, 2 T1/E1 controllers (See note 3.)		
		NM HDV2 1T1/E1	1-port T1/E1 IP Communications HD voice/fax		
		NWI HDV2 I I I/EI	NM, 1 T1/E1 controllers (See note 4.)		
		VWIC2 1MFT T1/E1	Second Generation Voice/WAN Interface Card		
		V WICZ IVII I TI/EI	1-port RJ-48, Multiflex Trunk T1/E1 (See note 3.)		
		VIC2 2FXS	Voice Interface Card,		
		Not Applicable	2-port, RJ-11, Foreign Exchange Station IP Phone (with push-to-talk handset or with		
CP-7940G and CP-7960G	Load: P00308000700		standard handset)		
	<u>CP-7970G and CP-7971G-GE</u> Load: SCCP70.8-3-2S		IP Phone (with push-to-talk handset or with		
<u>CP-7970G and CP-7971G-GE</u>			standard handset)		
CD #011C 1 CD #00CC		NY 4 A 12 1.1	IP Phone (with push-to-talk handset or with		
<u>CP-7911G and CP-7906G</u>	Load:SCCP11.8-3-2S	Not Applicable	standard handset)		
CP-7941G, CP-7941G-GE, CP-7961G,			IP Phone (with push-to-talk handset or with		
and CP-7961G-GE	SCCP41.8-3-2S	Not Applicable	standard handset)		
CP-7942G and CP-7962G	Load:	Not Applicable	IP Phone (with push-to-talk handset or with		
<u> </u>	SCCP42.8-3-2S		standard handset)		
CP-7945G and CP-7965G	Load: SCCP45.8-3-2S	Not Applicable	IP Phone (with push-to-talk handset or with		
	Load:		standard handset) IP Phone (with push-to-talk handset or with		
<u>CP-7975G</u>	SCCP75.8-3-2S	Not Applicable	standard handset)		
	Load:		Í .		
7914 S000105000300		Not Applicable	Expansion module		
LEGEND:	ted GE - Gigabit Ethern		PBX 1 - Private Branch Exchange 1		
10/100BaseT - 10/100 Mbps (Baseband Operation, Twist Pair) Ethernet	IP phone.)	et (A Cisco part designator on their	PBX 1 - Private Branch Exchange 1 PMO - Program Management Office		
CCM - Cisco CallManager		ning Center Requirements	RJ - Registered Jack SCCP - Skinny Client Control Protocol		
CP - Cisco Phone DI - Drop and Insert	HD - High Density HDA - High Density	Analog	SCCP - Skinny Client Control Protocol SR - Service Release		
DID - Direct Inward Dialing	IOS - Internetwork C	Operating System	SUT - System Under Test		
DSN - Defense Switched Network E1 - European Basic Multiplex Rate (2.048 M	 IP - Internet Protoc bps) IPv6 - Internet Protoc 		T1 - Digital Transmission Link Level 1 (1.544 Mbps) TDM - Time Division Multiplexing		
EI - European Basic Multiplex Rate (2.048 M EM - Expansion Module		ability Test Command	TDM - Time Division Multiplexing V - Voice		
EVM - Extension Voice Module	Mbps - Megabits per s	econd	VE - Voice/Fax Enhanced		
Fax - facsimile	MCS - Media Converg		VIC - Voice Interface Card		
FXS - Foreign Exchange Station G - 10/100BaseT Ethernet (A Cisco part	MFT - Multiflex Trun NM - Network Mode		VWIC - Voice WAN Interface Card WAN - Wide Area Network		
designator on their IP phone.)	1 INCLWOIR MOUL				

- NOTES:

 Components bolded and underlined were tested by JITC. The other components in the family series were not tested; however, they utilize the same IOS software and hardware and JITC analysis determined them to be functionally identical for interoperability certification purposes and they are also certified for joint use.

 All of the SUT components covered under this certification met the IPv6 criteria with the exception of the Cisco 3745 and 3725. The 3745 and 3725 do not meet the critical IPv6 capability requirement in accordance with the GSCR, paragraph 1.7. However, components that are not currently IPv6 capable and have been identified by the vendor as having no migration path to IPv6, may be certified if the following criteria is met:

 a. The component must already be JITC certified and currently fielded within the DSN.

 b. There must be a certified, IPv6-capable component available for replacement. To meet this requirement Cisco has designated the 3845 and 3825 respectively as replacements for the

 - 3745 and 3725 Multiservice Access Routers
- These components support both T1 and E1; however, the E1 interface was not tested by JITC and is not approved for use within the DSN by the PMO. Since E1 interfaces are not required for a PBX 1, the risk of not testing is minor.
- The EM HDA 8FXS expansion module requires the EVM HD module. Up to two EM HDA 8FXS expansion modules are supported for each EVM HD.

Table 2. SUT Interoperability Test Summary

DSN Trunk Interfaces				
Interface & Signaling	Critical	Status	Remarks	
T1 CAS (DTMF, MFR1, DP)	No	Not Certified	Although the SUT supports T1 CAS, due to critical interoperability discrepancies discovered during testing, it is not certified. Wink start recognition is not within the required tolerance.\(^1\) An off-hook seizure below the minimum limit is treated as valid.\(^2\) A call fails to complete after trunk preemption.\(^3\) Calls that are attempted over a trunk that is broken or in a remote busy-out condition do not receive ICA.\(^4\) This interface is not certified by JITC and is not authorized for use within the DSN by the PMO. There is no overall operational impact because T1 CAS is not a required interface for a PBX 1.	
E1 CAS (DTMF, MFR1, DP)	No (Europe only)	Not Tested	This interface was not tested by JITC and is not authorized for use within the DSN by the PMO. Since E1 interfaces are not required for a PBX 1, the risk of not testing is minor.	
T1 ISDN PRI NI 1/2 (ANSI T1.619a)	Yes	Certified	Met all CRs and FRs with the following minor exception: Calls that are attempted over a trunk that is broken or in a remote busy-out condition do not receive an ICA. The operational impact is minor.	
E1 ISDN PRI (ITU-T Q.955.3)	No (Europe only)	Not Tested	This interface was not tested by JITC and is not authorized for use within the DSN by the PMO. Since E1 interfaces are not required for a PBX 1, the risk of not testing is minor.	
		DSN Li	ine Interfaces	
Interface & Signaling	Critical	Status	Remarks	
2-Wire Analog (GR-506-CORE)	Yes	Certified	Met all CRs and FRs with a minor configuration change ⁵ and the following minor exceptions: The SUT does not support an MLPP global diversion number. ⁶ The BNEA is not provided. ⁷ The operational impact is minor.	
ISDN BRI NI 1/2 (ANSI T1.619a)	No	Not Tested	This interface is not supported. This is not a required interface for a PBX 1.	
2-Wire Proprietary Digital	No	Not Tested	This interface is not supported. This is not a required interface for a PBX 1.	
VoIP	No	Certified	Met all CRs and FRs with the following minor exceptions: The SUT does not support an MLPP global diversion number. The BNEA is not provided. The operational impact is minor.	
	D	SN Feature	es and Capabilities	
Features and Capabilities	Critical	Status	Remarks	
Common Features	No	Certified	Met all CRs and FRs with the following minor exceptions: Full compliance of DSN Common Call Features was not met. 8, 9, 10, 11, 12, 13 The operational impact is minor.	
Attendant	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
Public Safety	No	Certified	All public safety features are conditional. The SUT met all CRs and FRs for E911. The SUT does not support the other public safety features. These features are not required for a PBX 1. 14	
Preset Conferencing	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
Nailed-up Connections	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
PAT	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
DSN Hotline Services	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
Network Management	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
ISDN Services (EKTS)	No	Not Tested	This feature is not supported. This is not a required feature for a PBX 1.	
Synchronization	Yes	Certified	Met all CRs and FRs. 15	
Reliability	Yes	Certified	Met all CRs and FRs.	
Security	Yes	See note 16.	See note 16.	
VoIP System	No	Certified	The SUT is certified for VoIP specifically with any certified ASVALAN posted on the DSN APL. See notes 17 and 18.	

 Table 2. SUT Interoperability Test Summary (continued)

	Network Gateways					
Gateway	Interface & Signaling	Critical	Status	Remarks		
	T1 CAS (DTMF, MFR1, DP)	No	Not Certified	Although the SUT supports T1 CAS, due to critical interoperability discrepancies discovered during testing, it is not certified. Wink start recognition is not within the required tolerance. An off-hook seizure below the minimum limit is treated as valid. A call fails to complete after trunk preemption. There is no overall operational impact because T1 CAS is not a required interface for a PBX 1.		
PSTN	E1 CAS (DTMF, MFR1, DP)	No (Europe only)	Not Tested	This interface was not tested by JITC and is not authorized for use within the DSN by the PMO. Since E1 interfaces are not required for a PBX 1, the risk of not testing is minor.		
	T1 ISDN PRI NI 1/2 (ANSI T1.607)	No	Certified	Met all CRs and FRs.		
	E1 ISDN PRI (ITU-T Q.931)	No (Europe only)	Not Tested	This interface was not tested by JITC and is not authorized for use within the DSN by the PMO. Since E1 interfaces are not required for a PBX 1, the risk of not testing is minor.		
DRSN	TPC 2-Wire Analog (GR-506-CORE)	Yes	Certified ¹⁹	Met all critical CRs and FRs.		
ANSI	APL - Approved Products List ASVALAN - Assured Services Voice Application Local Area Network BRI - Busy Not Equipped Announcement BRI - Basic Rate Interface AS - Channel Associated Signaling TRS - Capability Requirements DiSA - Defense Information Systems Agency PP - Dial Pulse DRSN - Defense Red Switch Network DSS - Defense Switched Network DSS - Digital Subscriber Signaling 1 DTMF - Dual Tone Multi-Frequency El European Basic Multiplex Rate (2.048 Mbps) Basic Emergency Service 911 EKTS - Electronic Key Telephone System RS - Feature Requirements GR-506-CORE - LSSGR: Signaling for Analog Interfaces GSCR - Generic Switching Center Requirements LSSGR: Signaling for Analog Interfaces GACA - Isolated Code Announcement		rk	JITC - Joint Interoperability Test Command LSSGR - Local Access and Transport Area (LATA) Switching Systems Generic Requirements Mbps - Megabits per second MFR1 - Multi-Evelency Recommendation 1 MLPP - Multi-Level Precedence and Preemption ms - milliseconds NI 1/2 - National ISDN Standard 1 or 2 PAT - Precedence Access Threshold PBX 1 - Private Branch Exchange 1 PM - Program Manager PNT - Preempt Notification Tone PRI - Primary Rate Interface PSTN - Public Switched Telephone Network Q.931 - Signaling Standard for ISDN Q.955.3 - ISDN Signaling standard for E1 MLPP SS7 - Signaling System 7 SUT - System Under Test T1 - Digital Transmission Link Level 1 (1.544 Mbps) T1.607 - ISDN Layer 3 Signaling Specification for Circuit Switched Bearer Service for DSS1 T1.619a - SS7 and ISDN MLPP Signaling Standard for T1		
ITU-T -	Integrated Services Digital Network International Telecommunication Union - Telecommunication Standardization Sector		ication	TDM - Time Division Multiplexing TPC - Twisted Pair Copper VoIP - Voice over Internet Protocol		

Table 2. SUT Interoperability Test Summary (continued)

- T1 CAS wink start recognition is not within the required tolerance of 100 ms to 350 ms. The SUT will only recognize a wink from 140 ms to 280 ms. Although this is a critical requirement for T1 CAS, there is no operational impact because T1 CAS is not required for a PBX 1.

 The SUT will treat any off-hook condition (ABCD Channel Associated Signaling bits high) of 12 ms or greater as a valid off-hook seizure and respond with a wink. In accordance with the
- requirements, signals that are less than 60 ms should be considered invalid. Although this is a critical requirement for T1 CAS, there is no operational impact because T1 CAS is not
- During a trunk preemption test over the T1 CAS from the far-end to the SUT, after the preemption occurred the call would fail to complete and no treatment was provided to the call originator. Although this is a critical requirement for T1 CAS, there is no operational impact because T1 CAS is not required for a PBX 1.
- Calls that are attempted over a trunk that is broken or in a remote busy-out condition do not receive an Isolated Code Announcement (ICA). The operational impact is minor because they are treated with a Blocked Precedence Announcement (BPA) and since a PBX 1 cannot support special command and control users, the operational impact is mitigated.

 To meet the requirement for interoperability with secure devices, specifically the L3 Omni Secure Wireline Terminal, a configuration change was required on the analog gateways. On the
- individual voice ports, the minimum and maximum settings for "timing hookflash in" had to be changed to a maximum value of 500 ms and a minimum value of 150 ms. Otherwise, a call that is placed between two Omni devices on the SUT will not disconnect when placed on hook
- The SUT does not support an MLPP global diversion number. Each station must be individually configured with a precedence diversion number. The operational impact is minor because they can configure the diversion settings for all of the stations provisioned on the switch from a single location.

 When a station classmarked by the SUT as non-preemptable is active with a call and a higher precedence call attempts to directly preempt it, the BNEA is not provided. The operational
- impact is minor because the call is forwarded to the MLPP alternate directory number that is specified in the station's configuration.

 Call Forward No Answer, Call Forward Busy, and Multi-Line Hunt Service are supported on both VoIP and analog stations. Call Forward Variable, Three-way Calling, Call Hold, Call Pick-up, and Call Transfer are supported on VoIP stations only. The following common call features are not supported by the SUT and therefore are not covered in this certification: Call-Waiting, Selective Call Rejection, and Denied Originating Service. These features are not required for a PBX 1.

 All of the features on the IP phones were tested using multiple line appearances. A minimum of two line appearances is required to meet the MLPP interoperability requirements for Call
- 10 Although the SUT does not support Precedence Call Waiting, they do support multiple call appearances on their VoIP stations. This provides the ability for a user to receive additional calls while active with another call. There is no operational impact.
- 11 A short "ping" ring is not provided when calls are forwarded. There is a minor operational impact.
- 12 A conference disconnect tone is not provided when a three-way conference originator is preempted. This only occurs when an analog station originates the first call. The operational impact is minor because the preempted user receives Preempt Notification Tone (PNT) and the other members remain connected.
- 13 When a ROUTINE call is placed to a hunt group, and a ring-no-answer condition occurs, the calling party is diverted to the MLPP alternate directory number. This configuration must be done to allow correct treatment to be provided to precedence calls above ROUTINE that are placed to the hunt group. The GSCR requires this only for Precedence above ROUTINE calls. There is no operational impact.
- 14 The SUT only supports E911 public safety features. The following public safety features are not supported and therefore are not covered in this certification: Trace of terminating calls, Outgoing call trace, Tandem call trace, and Trace of a call in progress. There is no operational impact because public safety features are not required for a PBX 1.

 To meet this requirement, a direct T1 interface must be connected between multiple gateways to synchronize timing of all TDM-based interfaces between gateways.

 Security is tested by DISA-led Information Assurance test teams and published in a separate report.

- 17 An IPv6 capable system or product, as defined in the GSCR, paragraph 1.7, shall be capable of receiving, processing, and forwarding IPv6 packets and/or interfacing with other systems and protocols in a manner similar to that of IPv4. IPv6 capability is currently satisfied by a vendor Letter of Compliance signed by the Vice President of the company. The vendor stated, in writing, compliance to the following criteria by 30 June 2008:
 - Conformant with IPv6 standards profile contained in the Department of Defense Information Technology Standards Registry (DISR).
 - b. Maintaining interoperability in heterogeneous environments and with IPv4.
 c. Commitment to upgrade as the IPv6 standard evolves.

 - d. Availability of contractor/vendor IPv6 technical support.
- All of the SUT components covered under this certification met the IPv6 criteria with the exception of the Cisco 3745 and 3725. The 3745 and 3725 do not meet the critical IPv6 capability requirement in accordance with the GSCR, paragraph 1.7. However, components that are not currently IPv6 capable and have been identified by the vendor as having no migration path to IPv6, may be certified if the following criteria is met:
 - The component must already be JITC certified and currently fielded within the DSN.
 - There must be a certified, IPv6-capable component available for replacement. To meet this requirement Cisco has designated the 3845 and 3825 respectively as replacements for the 3745 and 3725 Multiservice Access Routers.
- 19 Interoperability certification of the SUT does not constitute DRSN PM approval for connectivity to the DRSN. It is the user's responsibility to request connectivity approval directly from

Table 3. PBX 1 Requirements

	DSN Trunk Interfaces					
T46	Interfece Cuitical Requirements References					
Interface	Critical		Required or Conditional	References		
T1 CAS (MFR1, DTMF, DP)	No		 Framing (R) Line Code (R) Signaling (R) Alarm and Restoral Requirements (R) Alarm and Restoral Requirements (C) WWNDP (R) Outpulsing digit formats 	• GSCR Section 7 • GSCR Section 7 • GSCR Section 5 • GSCR Section 7.1.4 • GSCR Section 7.2.2 • GSCR Section 4.5.1 • GSCR Section 4.5.2		
E1 CAS (MFR1, DTMF, DP)	No (Europe only)	Trunking	 Routing (C) Trunk Groups (C) Call Processing (R) CAS to CCS trunk interworking (C) PCM-24/PCM-30 Interoperation (C) Direct Inward Dialing (C) 	 GSCR Section 4.2 GSCR Section 2.5.5 & 2.5.6 GSCR Section 4 applicable paragraphs GSCR Section 3.10 GSCR Section 7.3 GSCR Section 2.3.2 		
T1 ISDN PRI NI 1/2 (ANSI T1.619a)	Yes	Voice	MOS (R) MLPP (R) Secure cells (D)	CJCSI 6215.01B GSCR Section 3 applicable paragraphs CJCSI 6215.01B		
		Facsimile	Secure calls (R)Analog: TIA/EIA-465-A (R)	• CJCSI 6215.01B • DISR		
E1 ISDN PRI (ITU-T Q.955.3)	No (Europe only)	Data	Modem (VBD) (R) 56 kbps switched data (C: PRI only) 64 kbps switched data (C: PRI only) NX56 synchronous BER (C: PRI only) NX64 synchronous BER (C: PRI only) Secure data (STE/STU-III) (R)	• CJCSI 6215.01B • GSCR Section 3.10 • CJCSI 6215.01B		
		VTC	• ITU-T H.320 (R: PRI only)	• FTR 1080B-2002		
			DSN Line Interfaces			
2-Wire Analog	Yes	Access	DSN Line Interfaces Directory Number Identification (R) Loop Start Line (R: 2-Wire Analog only) Ground Start Line (R) Alerting Signals and Tones (R) WWNDP (R) Origination Treatments (R) Termination Treatment (R) Release Treatment (R) Interruption Treatment (R) Connections (R) Class of Service (C) Wuser access (R: 2-Wire Analog only) Analog busy/idle (R: 2-Wire Analog only)	• GSCR Section 2.1.1 • GSCR Section 5.2.1 • GSCR Section 5.2.2 • GSCR Section 5.5 • GSCR Section 4.5 • GSCR Section 4.1.1 • GSCR Section 4.1.2 • GSCR Section 4.1.3 • GSCR Section 4.1.4 • GSCR Section 4.1.5 • GSCR Section 4.1.5 • GSCR Section 4.1.6 • GSCR Section 4.3.3 • GSCR Section 4.3.4.1		
ISDN BRI NI 1/2 (ANSI T1.619a)	No	Voice	MOS (R) MLPP (R) Secure Calls (R)	CJCSI 6215.01B GSCR Section 3 applicable paragraphs CJCSI 6215.01B		
2-Wire Proprietary Digital	No	Facsimile Data	Analog: TIA/EIA-465-A (R) Modem (VBD) (R) 56 kbps switched data (C: BRI only) 64 kbps switched data (C: BRI only) NX56 synchronous BER (C: BRI only) NX64 synchronous BER (C: BRI only) Secure data (STE/STU-III) (R) ITU-T H.320 (R: BRI only)	DISR CJCSI 6215.01B GSCR Section 3.10 CJCSI 6215.01B FTR 1080B-2002		

 Table 3. PBX 1 Requirements (continued)

DSN Features & Capabilities				
Feature/ Capability	Critical	Requirements Required or Conditional	References	
p		Selective call rejection (C)	GSCR Section 2.1.2	
		• Denied originating service (C)	GSCR Section 2.1.3	
		Code restriction and diversion (C)	GSCR Section 2.1.4	
C	NI.	• Call waiting (C)	GSCR Section 2.1.5	
Common Features	No	• Three-way calling (C)	GSCR Section 2.1.6	
		Add-on transfer, conference calling, and call hold (C)	GSCR Section 2.1.7	
		• Call forwarding (C)	GSCR Section 2.1.8	
		• Call pick-up (C)	GSCR Section 2.1.9	
		Initiate all precedence levels (C)	GSCR Section 2.2.1	
		• Visual display (C)	GSCR Section 2.2.2	
		• Override class of service (C)	GSCR Section 2.2.3	
Attendant	No	• Override busy line (C)	GSCR Section 2.2.4	
		• Call deflection (C)	• GSCR Section 2.2.5	
		• Auto recall (C)	• GSCR Section 2.2.6	
		• Waiting queue (C)	• GSCR Section 2.2.7	
		Basic Emergency Service (911) (C)	GSCR Section 2.4.1	
		• Trace of terminating calls (C)	• GSCR Section 2.4.2	
Public Safety	No	• Outgoing call trace (C)	• GSCR Section 2.4.3	
r done barety	110	• Tandem call trace (C)	• GSCR Section 2.4.4	
		• Trace of a call in progress (C)	• GSCR Section 2.4.5	
		 Support 10 bridges; 1 originator and 20 conferees per bridge (C) 	• GSCR Section 2.4.3	
		Assign up to 20 address numbers per bridge (C)	• GSCR Section 2.6	
		Vise KXX codes for bridge access (C)	• GSCR Section 2.6	
		Conference notification recorded announcement (C)	• GSCR Section 2.6.1	
		` '	• GSCR Section 2.6.2	
Preset Conferencing	No	• Auto retrial and alternate address (C)	• GSCR Section 2.6.2	
		Bridge release (C)Lost connection (C)	• GSCR Section 2.6.4	
		N C	• GSCR Section 2.6.5	
		Secondary conferencing (C)Meet Me Conferencing (C)	• GSCR Section 2.6.6	
		Address translation (C)	• GSCR Section 2.0.0	
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	No	Between any two like terminations (C) DCM 24 and DCM 20 back CAS and CCS (C)	• GSCR Section 2.8	
NT '1 1		• PCM-24 and PCM-30, both CAS and CCS (C)	• GSCR Section 2.8	
Nailed-up Connections		• Supervision passed end-to-end for A/D or D/A (C)	• GSCR Section 2.8	
Connections		• Monitored and auto reconfigure (C)	• GSCR Section 2.8	
		• Support at least 10% of circuits as nailed-up (C)	• GSCR Section 2.8	
		Non-preemptable (C) Signature of the control	• GSCR Section 2.8	
		Classmark for/not for PAT screening (C) TRATE (C)	• GSCR Section 2.11.1	
		• 7 PAT mechanisms (C)	• GSCR Section 2.11.1	
		• Outgoing call screening (C)	• GSCR Section 2.11.1.1	
		• Functional structure (C)	• GSCR Section 2.11.1.2	
		• Simultaneous calls limitation (C)	• GSCR Section 2.11.1.3	
PAT	No	• Overflow process (C)	• GSCR Section 2.11.1.4	
		• Decrementing call-in-progress count (C)	• GSCR Section 2.11.1.5	
		• Call treatment (C)	• GSCR Section 2.11.1.6	
		• Queuing (C)	• GSCR Section 2.11.1.7	
		• Attendant calls (C)	• GSCR Section 2.11.1.8	
		Operations measurement registers (C)	• GSCR Section 2.11.1.9	
		Maintenance and Administration of thresholds (C)	• GSCR Section 2.11.1.10	
		Hotline restrictions (C)	• GSCR Section 2.12	
DSN Hotline	No	• Auto initiate (C)	• GSCR Section 2.12	
Services		Analog and digital (C)	• GSCR Section 2.12	
		Subscription basis (C)	• GSCR Section 2.12	
		Protected hotline calling (C)	• GSCR Section 2.12.1-4	

Table 3. PBX 1 Requirements (continued)

DSN Features & Capabilities (continued)					
Feature/ Capability	Critical	Requirements Required or Conditional	References		
Network Management	No	 Interfaces (C) Measurements and data generation (C) Fault management (C) Configuration management (C) Accounting management (C) Performance management (C) Network management controls (C) Remote access (C) 	 GSCR Section 9.1 GSCR Section 9.2 GSCR Section 9.3 GSCR Section 9.4 GSCR Section 9.5 GSCR Section 9.6 GSCR Section 9.7 GSCR Section 9.8 		
ISDN Services	No	Electronic Key Telephone Systems (EKTS) (C)	GSCR Section 10, table 10-3		
Synchronization	Yes	Line timing mode (R) Internal Stratum 4 (R)	• GSCR Section 11.1.1.2 • GSCR Section 11.1.2.2		
Reliability	Yes	• GR-512-CORE (R)	• GSCR Section 12.2		
Security	Yes	GR-815, STIGs, and DIACAP (replacement for DITSCAP) (R)	• GSCR Section 13		
		VoIP			
VoIP System	No	VoIP function is conditional. If VoIP is provided, all of the following requirements must be met: • Voice Quality with MOS of 4.0 or better (R) • Class of Service (CoS) and Quality of Service (QoS) (R) • ITU-T G.711 PCM CODEC (R) • Traffic Engineering (R) • Security (R) • Network management (R) • Line timing (R) • Internal Clock (R) • Latency ≤ 60 milliseconds (R) • Packet Loss (R) • IPv6 capable (R)	 GSCR Appendix 3, para. 3.2.1 GSCR Appendix 3, para. 3.3.2.1 GSCR Appendix 3, para. 3.2.2 GSCR Appendix 3, para. 3.2.4 GSCR Appendix 3, para. 3.2.4 GSCR Appendix 3, para. 3.3.4.2 GSCR Appendix 3, para. 3.2.6 GSCR Appendix 3, para. 3.2.6 GSCR Appendix 3, para. 3.2.7 GSCR Appendix 3, para. 3.2.7 GSCR Appendix 3, para. 3.3.1.3 GSCR Appendix 3, para. 3.2.8 and Section 1 para. 1.7 		

Table 3. PBX 1 Requirements (continued)

Network Gateways						
Gateway	Critical		Requirements Required or Conditional		References	
PSTN ¹	No	Trunking	 Positive Identification Control (C) On-Netting (C) Off-Netting (C) 	CJCSI 6215.01BCJCSI 6215.01BCJCSI 6215.01B		
DRSN ²	Yes	Access	 Alerting Signals and Tones (R) Call Processing (R) Call Treatments (R) Analog busy/idle (R) 		 GSCR Section 5.5 GSCR Section 4.4 GSCR Section 4.1 GSCR Section 4.3.4.1 	
DROIN	Voice		MOS (C) MLPP (C) Secure calls (C)		 CJCSI 6215.01B GSCR Section 3 applicable paragraphs CJCSI 6215.01B 	
BER - Bit Error Ratic BRI - Basic Rate Int C - Conditional CAS - Channel Assoc CCS - Common Chan CJCSI - Chairman of ti Instruction CODEC - Coder/Decode D/A - Digital to Ana DIACAP - DoD Informat Accreditation DISR - DoD IT Stand DITSCAP - DoD IT Secur Accreditation DOD - Department of DP - Dial Pulse DRSN - Defense Red S DSN - Defense Switc DTMF - Dual Tone Mt	ional Standards Institute of created Signaling and Signaling and Signaling are Joint Chiefs of Staff or log Conversion ion Assurance Certification Process ards Registry ity Certification and Process To Effense Switch Network and Signaling are supported by the Signalian Signal	G.711 GR GR-512 GR-815 GSCR H.320 IPv6 ISDN IT on and ITU-T kbps KXX LSSGR Mbps MFR1 MLPP MOS	80B-2002 - Video Teleconferencing Services - Standard for PCM of Voice Frequencies - Generic Requirement - CORE - LSSGR: Reliability, Section 12 - Generic Requirements For Network - Element/Network System (NE/NS) Security - Generic Switching Center Requirements - Narrow-band visual telephone systems and terminal equipment - Internet Protocol version 6 - Integrated Services Digital Network - Information Technology - International Telecommunication Union- Telecommunication Standardization Sector - kilobits per second - K= any number 2-8; X= any number 1-9	PAT PBX 1 PCM PCM-24 PCM-30 PRI PSTN Q.955.3 R SS7 STE STIGS STU-III T1 T1.619a TIA	Precedence Access Threshold Private Branch Exchange 1 Pulse Code Modulation Pulse Code Modulation - 24 Channels Pulse Code Modulation - 30 Channels Primary Rate Interface Public Switched Telephone Network ISDN Signaling Standard for E1 MLPP Required Signaling System 7 Secure Terminal Equipment Security Technical Implementation Guides Secure Telephone Unit -3rd generation Digital Transmission Link Level 1 (1.544 Mbps) SS7 and ISDN MLPP Signaling Standard for T1 Telecommunications Industry Association A Group 3 Facsimile Apparatus for Document Transmission Variable bit data Voice over Internet Protocol Video Teleconferencing Worldwide Numbering and Dialing Plan	
	and VTC service required TC services are not provided		re identical to DSN with the exception of MLPP.			

5. No detailed test report was developed in accordance with the Program Manager's request. JITC distributes interoperability information via the JITC Electronic Report Distribution (ERD) system, which uses Unclassified-But-Sensitive Internet Protocol Router Network (NIPRNet) email. More comprehensive interoperability status information is available via the JITC System Tracking Program (STP). The STP is accessible by .mil/gov users on the NIPRNet at https://stp.fhu.disa.mil. Test reports, lessons learned, and related testing documents and references are on the JITC Joint Interoperability Tool (JIT) at http://jit.fhu.disa.mil (NIPRNet), or http://j199.208.204.125 (SIPRNet). Information related to DSN testing is on the Telecom Switched Services Interoperability (TSSI) website at http://jitc.fhu.disa.mil/tssi.

6. The JITC point of contact is Mr. Edward Mellon, DSN 879-5159, commercial (520) 538-5159, FAX DSN 879-4347, or e-mail to edward.mellon@disa.mil. The JITC's mailing address is P.O. Box 12798, Fort Huachuca, AZ 85670-2798. The tracking number for the SUT is 0716901.

FOR THE COMMANDER:

Enclosure a/s

RICHARD A. MEADOR

Chief

Battlespace Communications Portfolio

Distribution:

Joint Staff J6I, Room 1E596, Pentagon, Washington, DC 20318-6000

Joint Interoperability Test Command, Liaison, ATTN: TED/JT1, 2W24-8C, P.O. Box 4502, Falls Church, VA 22204-4502

Defense Information Systems Agency, Net-Centricity Requirements and Assessment Branch, ATTN: GE333, Room 244, P.O. Box 4502, Falls Church, VA 22204-4502

Office of Chief of Naval Operations (N71CC2), CNO N6/N7, 2000 Navy Pentagon, Washington, DC 20350

Headquarters U.S. Air Force, AF/XICF, 1800 Pentagon, Washington, DC 20330-1800

Department of the Army, Office of the Secretary of the Army, CIO/G6, ATTN: SAIS-IOQ, 107 Army Pentagon, Washington, DC 20310-0107

U.S. Marine Corps (C4ISR), MARCORSYSCOM, 2200 Lester St., Quantico, VA 22134-5010 DOT&E, Net-Centric Systems and Naval Warfare, 1700 Defense Pentagon, Washington, DC 20301-1700

U.S. Coast Guard, CG-64, 2100 2nd St. SW, Washington, DC 20593

Defense Intelligence Agency, 2000 MacDill Blvd., Bldg 6000, Bolling AFB, Washington, DC 20340-3342

National Security Agency, ATTN: DT, Suite 6496, 9800 Savage Road, Fort Meade, MD 20755-6496

Director, Defense Information Systems Agency, ATTN: GS235, Room 5W24-8A, P.O. Box 4502, Falls Church, VA 22204-4502

Office of Assistant Secretary of Defense (NII)/DOD CIO, Crystal Mall 3, 7th Floor, Suite 7000, 1851 S. Bell St., Arlington, VA 22202

Office of Under Secretary of Defense, AT&L, Room 3E144, 3070 Defense Pentagon, Washington, DC 20301

U.S. Joint Forces Command, J68, Net-Centric Integration, Communications, and Capabilities Division, 1562 Mitscher Ave., Norfolk, VA 23551-2488

Defense Information Systems Agency (DISA), ATTN: GS23 (Mr. McLaughlin), Room 5w23, 5275 Leesburg Pike (RTE 7), Falls Church, VA 22041

ADDITIONAL REFERENCES

- (c) Joint Interoperability Test Command, Memo, "Special Interoperability Test Certification of Cisco CallManager (CCM) Version 4.2(3) Service Release (SR) 3, with Internetwork Operating System (IOS) Software Release 12.4(9) T1," 4 March 2008
- (d) Chairman of the Joint Chiefs of Staff Instruction (CJCSI) 6215.01B, "Policy for Department of Defense Voice Services," 23 September 2001
- (d) Defense Information Systems Agency (DISA), "Defense Switched Network (DSN) Generic Switching Center Requirements (GSCR), Errata Change 2," 14 December 2006, Revised 27 March 2007
- (e) Joint Interoperability Test Command, "Defense Switched Network Generic Switch Test Plan (GSTP), Change 2," 2 October 2006